

Arduino
UNO
Connections

D25P
CNCTRK
AZ/EL

8 X DIR	—————	2 X DIR
9 X STEP	—————	3 X STEP
11 Y STEP	—————	5 Y STEP
10 Y DIR	—————	4 Y DIR
GND	—————	18-25 GND

Ref. Arduino Sketch

http://ki4sbl.dodropin.org/CNCTRK/Arduino/RAZEL-duino_cmd-no-display.ino

CNCTRK / RAZEL Control Using Arduino UNO

R. Freeman

2016-05-25